

# STRUCTURIX<sup>®</sup> XXXX

## NDT X-ray Films Manual Processing Guide

D E V E L O P E R

Temp. (Farenheit)

64°  
6: min. 00 sec.

Temp. (Farenheit)\*

68°\*  
5: min. 00 sec.

Temp. (Farenheit)

72°  
4: min. 00 sec.

Temp. (Farenheit)

75°  
3: min. 30 sec.

\*Standard Processing Temperature/Time

Temp. (Farenheit)

79°  
3: min. 00 sec.

Temp. (Farenheit)

82°  
2: min. 30 sec.

Temp. (Farenheit)

86°  
2: min. 00 sec.

**AGFA** 

© Copyright 1990 Agfa Corp.

A G I T A T E

**Developer & Fixer** Agitate 5 seconds every 30 seconds during processing.